

Remarks:
SL / ECLK cannot be driven by other circuit in application.
Otherwise, programmer cannot output signal to the IC properly.





Title		
Size: A4	Number	Revision
Date: 21/5/2018		Sheet of
File: D:\Danny\..\DC6288FT32-SCH-Rev1.0.SchDoc		Drawn By: